

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

570

1. Name of the owner of the structure :

Kime Nime

2. Name of the owner the structure :

33000

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

RCC Slab

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr )

b) Banderdewa end (mtr)

6. Breadth of the structure (mtr)

7. Total area of the structure in square metre

8. Photograph of the structure (enclosed)

$$\left( \frac{22.10 \times 1.10}{2} \right) \times 2 = 24.31 \text{ Sqm}$$
$$\left( \begin{matrix} 9.20 \\ 1.20 \end{matrix} \right) \times 1 = 11.04 \text{ Sqm}$$


4+2  
24  
= 24.31 Sqm  
36.465

Area of (4.40 x 1.40) = 6.16 Sqm

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

18/8/17

Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)



FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

51 (2)

1. Name of the owner of the structure

: Kago Talao

2. Name of the owner the structure

: 33500

3. Chainage/Location of the structure

:

4. Type of structure (whether RCC/SPT/MIBT/OBT):

RCC Slab

5. Length of the structure ( Mtr)

:

a) Itanagar end ( mtr )

:  $(3.90 \times 1.80)$  <sup>GH</sup> <sub>2</sub>

b) Banderdewa end (mtr)

RCC Slab

=  $\frac{7.02}{1.04} \text{ sqm}$

6. Breadth of the structure (mtr)

:

7. Total area of the structure in square metre

CC Slab

:  $5.00 \times 1.70$

= 8.5 sqm

8. Photograph of the structure (enclosed)

:

Executive Engineer  
Naharlagun Highway Division  
PWD:AP, Nirjuli.


Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)

90 (3)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure : Komkar Jyoti
2. Name of the owner the structure : 33520
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): RCC
5. Length of the structure ( Mtr) :
- a) Itanagar end ( mtr ) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 3.20 x 1.90
7. Total area of the structure in square metre : = 6.08 sqm
8. Photograph of the structure (enclosed) :

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

  
Extra Assistant Commissioner  
Itanagar Capit. Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

49 (4)

1. Name of the owner of the structure :

Naren Rao

2. Name of the owner the structure :

SS 33807

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr ) :

b) Banderdewa end (mtr) :

6. Breadth of the structure (mtr)

MIBT : (4.10 x 2.70)

7. Total area of the structure in square metre

Tin Shed: (3.70 x 1.40) = 11.07 sqm  
~~OBT : (3.70 x 1.40)~~

8. Photograph of the structure (enclosed)

Rm

✓ Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

48 (5)

1. Name of the owner of the structure : Nareen Taw

2. Name of the owner the structure : 33640

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr ) :

b) Banderdewa end (mtr)

OBT - :  $3.50 \times 2.50 = 8.75 \text{ sqm}$

6. Breadth of the structure (mtr)

MIBT :  $3.20 \times 6.50 = 20.80 \text{ m}$

7. Total area of the structure in square metre

SPT :  $= 6.50 \times 3.50 = 22.75 \text{ m}$

8. Photograph of the structure (enclosed)

✓ Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

Janyas

Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

41 (6)

1. Name of the owner of the structure : Dusu Bath
2. Name of the owner the structure : 53610
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): MIBT
5. Length of the structure ( Mtr) :
  - a) Itanagar end ( mtr ) :
  - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 400 x 6.60
7. Total area of the structure in square metre :  
= 2640 Sqm
8. Photograph of the structure (enclosed) :

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

Dusu Akh

  
Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure :

Radi Yari

2. Name of the owner the structure :

33720

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

SPT

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr ) :

b) Banderdewa end (mtr) :


6. Breadth of the structure (mtr) :


$\frac{9.80 \times 2.7}{2}$


7. Total area of the structure in square metre :


8. Photograph of the structure (enclosed) :

= 13.23 Sqm

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.





  
Extra Assistant Commissioner  
Itanagar Capit. Complex  
Itanagar (A.P)

26  
8

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure :

Fakir Nyigora

2. Name of the owner the structure :

33750

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr )

Rec Stair

:  $4.30 \times 1.50 = 6.45 \text{ sqm}$

b) Banderdewa end (mtr)

6. Breadth of the structure (mtr)

Rec Room

:  $(2.70 \times 14.30) \times 1.3 = 48.6$


7. Total area of the structure in square metre

CC Staircase


:  $2.50 \times 3.40 = 8.50$

8. Photograph of the structure (enclosed) :

= 8.50 sqm

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.



  
Extra Assistant Commissioner  
Itanagar Capit. Complex  
Itanagar (A.P)



FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

44  
⑨

1. Name of the owner of the structure

: Alin Lego

2. Name of the owner the structure

: 337/00

3. Chainage/Location of the structure

:

4. Type of structure (whether RCC/SPT/MIBT/OBT):

RCC

5. Length of the structure ( Mtr)

:

a) Itanagar end ( mtr )

:

b) Banderdewa end (mtr)

:

6. Breadth of the structure (mtr)

:

G+3  
(13.20 x 4.20)


7. Total area of the structure in square metre

:

8. Photograph of the structure (enclosed)

:

= 55.44 sqm

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

  
Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

47 (10)


- 1. Name of the owner of the structure : Yamak Tava Tava
- 2. Name of the owner the structure :
- 3. Chainage/Location of the structure :
- 4. Type of structure (whether RCC/SPT/MIBT/OBT): Rec Slab
- 5. Length of the structure ( Mtr) :
- a) Itanagar end ( mtr ) :
- b) Banderdewa end (mtr) :
- 6. Breadth of the structure (mtr)
- 7. Total area of the structure in square metre
- 8. Photograph of the structure (enclosed) :

$$\left( \begin{array}{l} : 9.00 \\ : 3.00 + 1.50 \\ \hline 2 \end{array} \right) = 20.25 \text{ Sqm}$$
  
$$1.40 \times 1.00 = 1.40 \text{ Sqm}$$

Area -



Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.




Extra Assistant Commissioner  
Managar Capital Complex  
Itanagar (A.P)

92/11

FORMAT FOR VERIFICATION REPORT  
(Right hand side/Left hand side)

1. Name of the owner of the structure : Yanga Gango
2. Name of the owner the structure : 33900
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): RCC
5. Length of the structure ( Mtr) :
- a) Itanagar end ( mtr ) : 9.70
- b) Banderdewa end (mtr) :  $\frac{2.30 + 3.90}{2}$
6. Breadth of the structure (mtr) :
7. Total area of the structure in square metre :
8. Photograph of the structure (enclosed) : = 30.07 Sqm

✓ Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.



**FORMAT FOR VERIFICATION REPORT**  
**(Right Hand Side/Left Hand Side)**

1. Name of the owner of the structure : Broken Nake  
2. Chainage/Location of the structure : 33830  
3. Type of the structure (whether RCC/SPT/MIBT/OBT) : RCC

4. No. of floors :

5. Length of the structure (Mtr)

(a) Itanagar end (Mtr)

(b) Banderdewa end (Mtr)



6. Breadth of the structure (Mtr)

7. Total area of the structure in square meters

8. Photograph of the structure (enclosed)

$$\begin{aligned}
 & \text{G13} \\
 & A \left( \frac{13 \times 380 + 4.6 + 4.40}{3} \right) = 55.46 \\
 & \text{G12} \\
 & B \left( \frac{11.40 \times 2.80 + 3.00 + 3.4 + 4.2}{4} \right) = 38.17 \\
 & = 114.57 \\
 & \text{RCC wall} = 20 \times 1.40 \\
 & \hline
 & 336.47 \text{ Sqm}
 \end{aligned}$$

$$\begin{aligned}
 & \text{RCC wall} = 20 \times 1.40 \\
 & = 28.00 \text{ Sqm}
 \end{aligned}$$



✓  
(Executive Engineer)  
Naharlagun Highway Division  
PWD, Nirjuli.

Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

40  
13

1. Name of the owner of the structure :

Nabam Yaki

2. Name of the owner the structure :

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

RCC

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr ) :

b) Banderdewa end (mtr) :

6. Breadth of the structure (mtr) :

$$7.30 \times \frac{3.70 + 2.40}{2}$$

7. Total area of the structure in square metre :


$$= 22.265 \text{ sqm}$$

8. Photograph of the structure (enclosed) :

$$\frac{9.30 \times 0.90}{2}$$

$$= 4.185 \text{ sqm}$$

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.



Handwritten signature

Extra Assistant Commissioner  
Itanagar Capital Complex  
Naharlagun, A.P.

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

99 (14)

1. Name of the owner of the structure : Rizio Yaluru

2. Name of the owner the structure : 33930

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT): RCC

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr )

b) Banderdewa end (mtr)

G+1

$$\frac{15 \times 1.70 + 2.50 \times 2.70}{2} + 2$$

6. Breadth of the structure (mtr) :


7. Total area of the structure in square metre :  $5 \times \frac{2.50 + 1.70}{2} = 10.50$  sqm

8. Photograph of the structure (enclosed) :  $6 \times \frac{2.70 + 2}{2} = 14.10$  sqm



Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

$$\left( \frac{1.50 \times 15}{2} \right) \text{ slab} = 3.50 \text{ sqm}$$




Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar, A.P.

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

28/15

1. Name of the owner of the structure : P. Masingy
2. Name of the owner the structure : 34000
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): RCC
5. Length of the structure ( Mtr) :
- a) Itanagar end ( mtr ) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) :
7. Total area of the structure in square metre :  
RCC Room  $(2.20 \times 2.40) = 4.68 \text{ Sqm}$
8. Photograph of the structure (enclosed) :  
Ramp :  $2.30 \times 1.80 = 4.14 \text{ Sqm}$   
P. Masingy

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

  
Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar :A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

377 (16)

1. Name of the owner of the structure :

Opang Apang

2. Name of the owner the structure :

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

RCC

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr ) :

b) Banderdewa end (mtr) :

6. Breadth of the structure (mtr) :

7. Total area of the structure in square metre

RCC Room

$$\begin{matrix} \text{GHI} \\ (2.80 \times 1.60) \times 2 \\ = 4.48 \end{matrix}$$

8. Photograph of the structure (enclosed)

CC Kap

$$2.90 \times 1.46 = 4.06$$

*[Handwritten signature]*

*[Handwritten signature]*

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

*[Handwritten signature]*  
Extra Assistant Commissioner  
Itanagar Capit. Complex  
Itanagar (A.P)



FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

17

1. Name of the owner of the structure : Dibag Tatar
2. Name of the owner the structure : 34010 - 34020
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): RCC
5. Length of the structure ( Mtr) :
  - a) Itanagar end ( mtr ) :
  - b) Banderdewa end (mtr) RCC Room -  $(3.20 \times 2.70) = 8.64$
6. Breadth of the structure (mtr) RCC Room -  $(4.10 \times 2.30) = 9.43$
7. Total area of the structure in square metre :  $\frac{18.079}{}$
8. Photograph of the structure (enclosed) Staircase =  $(6.00 \times 1.60) 2$   
 $= 19.20$   
sqm

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.


  
Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)


35 (18)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure : *Bhargav Davary*
2. Name of the owner the structure : *340410*
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): *SPT*
5. Length of the structure ( Mtr) :
  - a) Itanagar end ( mtr ) *MIBT* :  $1.60 \times 1.80 = 2.88 \text{ sqm}$
  - b) Banderdewa end (mtr) *RCC for staircase* :  $1.80 \times 2.30 = 4.14 \text{ sqm}$
6. Breadth of the structure (mtr) :
7. Total area of the structure in square metre *RCC Room:*  $1.10 \times 2.70 = 2.97 \text{ sqm}$
8. Photograph of the structure (enclosed) : *O. Davary*  
*4/8/2017*

✓   
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

  
Extra Assistant Commissioner  
Itanagar Capit. Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure

: Tanya Rikong

2. Name of the owner the structure

: 34090

3. Chainage/Location of the structure

:

4. Type of structure (whether RCC/SPT/MIBT/OBT):

G+2

5. Length of the structure ( Mtr)

:

a) Itanagar end ( mtr )

b) Banderdewa end (mtr)

Slab ( 11.00 ) x 2  
: 1.40 = 15.40 sqm

6. Breadth of the structure (mtr)

7. Total area of the structure in square metre

RCC Room: ( 4.50 x 1.80 )  
: 8.10 sqm

8. Photograph of the structure (enclosed)

RCC Room = 3.50 x 2.90  
= 10.15 sqm


RCC Room = 3.60 x 1.50  
= 5.40 sqm

~~RCC Slab = 4.10 x 3.5~~

MIBT = 3.50 x 4.50

= 15.75 sqm

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.




Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)


33 (20)

FORMAT FOR VERIFICATION REPORT  
(Right hand side/Left hand side)

1. Name of the owner of the structure : Bini Kakum
2. Name of the owner the structure : Kakum
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): MIBT
5. Length of the structure ( Mtr) :
- a) Itanagar end ( mtr ) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : ~~3.50~~  
6.60 x 3.20
7. Total area of the structure in square metre :
8. Photograph of the structure (enclosed) : = 21.12 sqm

*Handwritten initials/signature*

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.


  
Extra Assistant Commissioner  
Itanagar Capit. Complex  
Itanagar (A.P)


FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

32/2

- 1. Name of the owner of the structure : Byabang Rama
- 2. Name of the owner the structure : 44/50
- 3. Chainage/Location of the structure :
- 4. Type of structure (whether RCC/SPT/MIBT/OBT): RCC
- 5. Length of the structure ( Mtr) :
- a) Itanagar end ( mtr ) :
- b) Banderdewa end (mtr) :
- 6. Breadth of the structure (mtr) : Floor slab :  $\frac{6.60 \times 1.10}{2} = 3.63 \text{ sqm}$
- 7. Total area of the structure in square metre :
- 8. Photograph of the structure (enclosed) : Brick wall -  $1.20 \times 2.20 = 2.64 \text{ sqm}$

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

Not to be  
  
upload



  
Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar - A.P1

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

31 (22)

1. Name of the owner of the structure

: Hitesh Khode

2. Name of the owner the structure

: B3060

3. Chainage/Location of the structure

:

4. Type of structure (whether RCC/SPT/MIBT/OBT):

: Truss Shed

5. Length of the structure ( Mtr)

:

a) Itanagar end ( mtr )

:

b) Banderdewa end (mtr)

:

6. Breadth of the structure (mtr)

:

: 3.20 X 1.80

7. Total area of the structure in square metre


:

8. Photograph of the structure (enclosed)

:

= 5.76 sqm

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.



Extra Assistant Commissioner  
Itanagar Capri. Complex  
Itanagar - A.P.

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

30 (23)

1. Name of the owner of the structure

: Higo Tamen

2. Name of the owner the structure

: 32060

3. Chainage/Location of the structure

:

4. Type of structure (whether RCC/SPT/MIBT/OBT):

RBT

5. Length of the structure ( Mtr)

:

a) Itanagar end ( mtr )

:

b) Banderdewa end (mtr)

:

6. Breadth of the structure (mtr)

RBT

:

7. Total area of the structure in square metre

:

8. Photograph of the structure (enclosed)

RBT

:

$(3.00 \times 8.10)$   
 $= 24.30 \text{ sqm}$   
 $(7.50 \times 2.40)$   
 $= 18.00 \text{ sqm}$

✓ Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

29 (29)

1. Name of the owner of the structure :

name Bengia  
~~Bengia name~~  
33350

2. Name of the owner the structure :

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

RCC

5. Length of the structure ( Mtr) :

a) Itanagar end ( mtr ) :

b) Banderdewa end (mtr) :

6. Breadth of the structure (mtr) :

$$\frac{3.5 \times 3.4}{2}$$


7. Total area of the structure in square metre :

2

8. Photograph of the structure (enclosed) :

$$= 5.95 \text{ sqm}$$

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.



Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)





FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

26  
25

1. Name of the owner of the structure : Robin Mory
2. Name of the owner the structure : 33420
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): Tin Shed
5. Length of the structure ( Mtr) :
  - a) Itanagar end ( mtr ) :
  - b) Banderdewa end (mtr) : (3.30 x 5.10)
6. Breadth of the structure (mtr) :
7. Total area of the structure in square metre :
8. Photograph of the structure (enclosed) : 16.83 sqm

  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

  
Extra Assistant Commissioner  
Itanagar Capit. Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

27 (26)

1. Name of the owner of the structure

: Neha Kamin

2. Name of the owner the structure

: 330460

3. Chainage/Location of the structure

:

4. Type of structure (whether RCC/SPT/MIBT/OBT):

Tin shed

5. Length of the structure ( Mtr)

:

a) Itanagar end ( mtr)

:

b) Banderdewa end (mtr)

:

6. Breadth of the structure (mtr)

7. Total area of the structure in square metre

8. Photograph of the structure (enclosed)

Tin

Tin shed (6.00 x 2.40)  
= 14.40  
3.40 x 2.40  
8.16  

---

22.56 sqm

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

Extra Assistant Commissioner  
Itanagar Capit. Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

26 (27)

1. Name of the owner of the structure :

Bini Lakum

2. Name of the owner the structure :

3. Chainage/Location of the structure :

4. Type of structure (whether RCC/SPT/MIBT/OBT):

RCC

5. Length of the structure ( Mtr) :

67.2

a) Itanagar end ( mtr) :

b) Banderdewa end (mtr) :



6. Breadth of the structure (mtr)

7. Total area of the structure in square metre

8. Photograph of the structure (enclosed)

$$\left( \begin{array}{l} 16.80 \\ 1.70 + 1.40 \\ \hline 2 \end{array} \right) \times 2 = 13.02 = 26.04 \text{ sqm}$$

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.



Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)

5 (28)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure :
2. Name of the owner the structure :
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT):
5. Length of the structure ( Mtr ) :
- a) Itanagar end ( mtr ) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) :
7. Total area of the structure in square metre :
8. Photograph of the structure (enclosed) :

Taringapak


MIBT

$$14.70 \times \frac{2.17 + 2.70}{2}$$

$$= 51.74 \text{ sqm}$$

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.

*(Signature)*



Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)


FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

24 (29)

1. Name of the owner of the structure : Kabak Anonoy
2. Name of the owner the structure : 34630
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): MIBT
5. Length of the structure ( Mtr) :
  - a) Itanagar end ( mtr ) :
  - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) :  $\frac{7.80 \times 2.00}{2}$
7. Total area of the structure in square metre : 7.90 Sqm
8. Photograph of the structure (enclosed) :

Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.



Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

27 (30)

- 1. Name of the owner of the structure : Toko Sama
- 2. Name of the owner the structure : 34650
- 3. Chainage/Location of the structure :
- 4. Type of structure (whether RCC/SPT/MIBT/OBT):
- 5. Length of the structure ( Mtr) : 67.2
  - a) Itanagar end ( mtr ) :
  - b) Banderdewa end (mtr) : (23.30 x 1.50) ~~1.2~~
- 6. Breadth of the structure (mtr) :
- 7. Total area of the structure in square metre :
- 8. Photograph of the structure (enclosed) : = 34.75 Sqm

*[Handwritten signature]*

✓ *[Signature]*  
Executive Engineer  
Naharlagun Highway Division  
PWD:AP,Nirjuli.



*[Signature]*  
Extra Assistant Commissioner  
Manager Capital Complex  
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

22/31

1. Name of the owner of the structure : Ompa Pongte
2. Name of the owner the structure : 34868
3. Chainage/Location of the structure :
4. Type of structure (whether RCC/SPT/MIBT/OBT): Brick Wall
5. Length of the structure ( Mtr) :
  - a) Itanagar end ( mtr ) :
  - b) Banderdewa end (mtr) : 6.80 x 2.50
6. Breadth of the structure (mtr) : ~~2.00 x 2.50~~
7. Total area of the structure in square metre :
8. Photograph of the structure (enclosed) : 17.00 sqm

N. Pongte

↓  
Executive Engineer  
Nahadagun Highway Division  
PWD:AP,Nirjuli.

Extra Assistant Commissioner  
Itanagar Capital Complex  
Itanagar (A.P)