

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

128

①

1. Name of the owner of the structure : Nalam Binyi
2. Chainage/Location of the structure : 29500 - 29600
3. Type of structure (whether RCC/SPT/MIBT/OBT): OBT
4. No. of Floors :
5. Length of the structure (mtr) : 4.1
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2.1
7. Total area of the structure in square metre : 8.61m²
8. Photograph of the structure (enclosed) :

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

Chandranagar

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

12X

②

1. Name of the owner of the structure : Tabu Dayam
2. Chainage/Location of the structure : 29600 - 29700
3. Type of structure (whether RCC/SPT/MIBT/OBT): Rec
4. No. of Floors : 4+2
5. Length of the structure (mtr) : 21.30
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 7.1
7. Total area of the structure in square metre : $151.23 \times 3 = 453.69$
8. Photograph of the structure (enclosed) :

Executive Engineer
Naharlagun Highway Division
PWB:AP,Nirjuli.



Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)



FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

126

3

1. Name of the owner of the structure : Tai Sorang
2. Chainage/Location of the structure : 29600 - 29700
3. Type of structure (whether RCC/SPT/MIBT/OBT): OBT
4. No. of Floors :
5. Length of the structure (mtr) : 7.3
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 7.1
7. Total area of the structure in square metre : $51.83 m^2$
8. Photograph of the structure (enclosed) :
OBT : $9 \times 5.2 = 46.8 m^2$

 $98.63 m^2$

✓
Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

Tai Sorang
Jup

✓
Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)


125


(4)


FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure : Tai Srang
2. Chainage/Location of the structure : 29600 - 29700
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : G+1
5. Length of the structure (mtr) : 5.00
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 9.00
7. Total area of the structure in square metre : 45m²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capit. Complex
Itanagar (A.P)



FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

124

5

1. Name of the owner of the structure : Bulang Marik
2. Chainage/Location of the structure : 29700-29800
3. Type of structure (whether RCC/SPT/MIBT/OBT): Steel Stair Case
4. No. of Floors :
5. Length of the structure (mtr) : $2 \times 3 = 6$
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : $2 \times 1.1 = 2.2$
7. Total area of the structure in square metre : 7.3 m^2
8. Photograph of the structure (enclosed) :

✓
Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

127⁶

1. Name of the owner of the structure : R. Rao
2. Chainage/Location of the structure : 29800-29900
3. Type of structure (whether RCC/SPT/MIBT/OBT): Under Construction (PL)
4. No. of Floors :
5. Length of the structure (mtr) : 22.5
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 12.1
7. Total area of the structure in square metre : 272.25m²
8. Photograph of the structure (enclosed) :

✓
Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

✓

Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P.)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

②
122

1. Name of the owner of the structure : R. Tare
2. Chainage/Location of the structure : 29800-29900
3. Type of structure (whether RCC/SPT/MIBT/OBT): R/wall
4. No. of Floors :
5. Length of the structure (mtr) : 15
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2
7. Total area of the structure in square metre : $15m \times 2 = 30m^2$
8. Photograph of the structure (enclosed) :

✓
Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


~~Signature~~

~~Signature~~
Extra Assistant Commissioner
Itanagar Sapir Complex
Itanagar (A.P)


121 8

FORMAT FOR VERIFICATION REPORT
(Right hand side/Left hand side)

1. Name of the owner of the structure : *Dalam Tade*
2. Chainage/Location of the structure :
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : *10.00*
- a) Itanagar end (mtr) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : *0.5*
7. Total area of the structure in square metre : *8m²*
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.





Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

120⁹

1. Name of the owner of the structure : Ellang Tallang
2. Chainage/Location of the structure : 30100 - 30200
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : 4+1
5. Length of the structure (mtr) : 26.5
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 6.6
7. Total area of the structure in square metre : 174.9ms²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagon Highway Division
PVD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

129 (10)

1. Name of the owner of the structure : Tugu Gangalak
2. Chainage/Location of the structure : 30250 - 30300
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : 4/2
5. Length of the structure (mtr) : 4
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2
7. Total area of the structure in square metre : 8m²
8. Photograph of the structure (enclosed) :

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

Ajay K S Singh
9402257576


Extra Assistant Commissioner
Itanagar Capir Complex
Itanagar (A.P)


FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

118 (10)

1. Name of the owner of the structure : Pugo Gangalak
2. Chainage/Location of the structure : 30200 - 30300
3. Type of structure (whether RCC/SPT/MIBT/OBT): Brick wall
4. No. of Floors :
5. Length of the structure (mtr) : 29.00
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2
7. Total area of the structure in square metre : 58m²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Aiyas K S Siran
9402257576



Extra Assistant Commissioner
Itanagar Capir- Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

117 (24)

1. Name of the owner of the structure : Hage Tatan
2. Chainage/Location of the structure : 30200 - 30300
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 8.1
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 1.7
7. Total area of the structure in square metre : 13.97m²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.




Extra Assistant Commissioner
Itanagar Capr. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

116 13

1. Name of the owner of the structure : *Atige Tatan*
2. Chainage/Location of the structure : *30200 - 30300*
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : *4+2*
5. Length of the structure (mtr) : *14*
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : *4.6*
7. Total area of the structure in square metre : *64.4m²*
8. Photograph of the structure (enclosed) :
water Tank : *3x3 = 9m²*

✓
Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

Oh
3/8/12

[Signature]
Extra Assistant Commissioner
Itanagar Capit. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

115

1. Name of the owner of the structure : Hage Yaku
2. Chainage/Location of the structure : 30200 - 30300
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : G+2
5. Length of the structure (mtr) : 13
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 7.3
7. Total area of the structure in square metre : $94.9m^2$
8. Photograph of the structure (enclosed) :
9. ec floor : $7.5 \times 3.4 = 25.5m^2$
10. under lane : $3 \times 3 = 9m^2$

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

3.8.2017.
For Hage Yaku.

Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar A.P.I

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

114

1. Name of the owner of the structure : Radhe Raja
2. Chainage/Location of the structure : 30400 - 20600
3. Type of structure (whether RCC/SPT/MIBT/OBT): Stair Case
4. No. of Floors :
5. Length of the structure (mtr) : 4.7
- a) Itanagar end (mtr) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 1.3
7. Total area of the structure in square metre : 6.11m²
8. Photograph of the structure (enclosed) :

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

03/08/2017

Extra Assistant Commissioner
Itanagar Capri. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

119

1. Name of the owner of the structure : H. Natung
2. Chainage/Location of the structure : 30300 - 30400
3. Type of structure (whether RCC/SPT/MIBT/OBT): Rec
4. No. of Floors :
5. Length of the structure (mtr) : 5.8
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 3.9
7. Total area of the structure in square metre : $22.62m^2$
8. Photograph of the structure (enclosed) : $6.5 \times 2.6 = 16.9m^2$
Rec. Mg. $\frac{16.9m^2}{39.52m^2}$

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

112 H

1. Name of the owner of the structure : Buler Tedi
2. Chainage/Location of the structure : 30360 - 30400
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 4.2
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 6.4
7. Total area of the structure in square metre : $26.88 m^2$
8. Photograph of the structure (enclosed) :
9. Brick wall : $44m \times 2 = 88m^2$

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

111

1. Name of the owner of the structure : R. Jini
2. Chainage/Location of the structure : 20400 - 30350
3. Type of structure (whether RCC/SPT/MIBT/OBT): SPT
4. No. of Floors :
5. Length of the structure (mtr) : 7.7
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 3.6
7. Total area of the structure in square metre : $27.72m^2$
8. Photograph of the structure (enclosed) :
9. Tube well : 2 nos $1.35 \times 7.2 \times 2$
10. MIBT : $7.7 \times 2 = 15.4m^2$

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

[Signature]
03/08/2017


[Signature]
Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)


FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

110
19

1. Name of the owner of the structure : *Kand Ado*
2. Chainage/Location of the structure : *30400 - 30500*
3. Type of structure (whether RCC/SPT/MIBT/OBT): *SPT*
4. No. of Floors :
5. Length of the structure (mtr) : *5*
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : *2.5*
7. Total area of the structure in square metre : *12.5 m²*
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


03/08/17



Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P.)


FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

109²⁰

1. Name of the owner of the structure : D. Etc
2. Chainage/Location of the structure : 30400 - 30500
3. Type of structure (whether RCC/SPT/MIBT/OBT): wall
4. No. of Floors :
5. Length of the structure (mtr) : 32.2
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2
7. Total area of the structure in square metre : 64.4 m²
8. Photograph of the structure (enclosed) :
Arch gate : 1 Nos


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



3/10/17



Extra Assistant Commissioner
Itanagar Capit. Complex
Itanagar (A.P)

108 ✓

FORMAT FOR VERIFICATION REPORT
(Right Hand Side/Left Hand Side)

1. Name of the owner of the structure :
2. Chainage/Location of the structure : 30550 - 30600
(Near VCS upside school)
3. Type of the structure (whether RCC/SPT/MIBT/OBT) : Ramp CC
4. No. of floors :
5. Length of the structure (Mtr) 12
(a) Itanagar end (Mtr) :
(b) Banderdewa end (Mtr) :
6. Breadth of the structure (Mtr) : 5.2
7. Total area of the structure in square meters : 62.4 m²
8. Photograph of the structure (enclosed) :


Extra Assistant Commissioner
Itanagar Capit. Complex
Itanagar (A.P)


(Executive Engineer)
Naharlagun Highway Division
PWD, Nirjuli.


107 24


FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure : Tolko Salcha (Salcha)
2. Chainage/Location of the structure : 30700 - 30800
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 24.2
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) . :
6. Breadth of the structure (mtr) : 2.8
7. Total area of the structure in square metre : 67.76m²
8. Photograph of the structure (enclosed) :




✓

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

10/6 27

FORMAT FOR VERIFICATION REPORT
(Right hand side/Left hand side)

1. Name of the owner of the structure :
2. Chainage/Location of the structure : ~~267~~ 30700 30800
3. Type of structure (whether RCC/SPT/MIBT/OBT): CC Platform
4. No. of Floors :
5. Length of the structure (mtr) : 26.1
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 6.3
7. Total area of the structure in square metre : 164.43ms²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

105
29

1. Name of the owner of the structure : Bida Gadi
2. Chainage/Location of the structure : 30800 - 30900
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : G+1
5. Length of the structure (mtr) : 16.5
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2.4
7. Total area of the structure in square metre : $39.6m^2$
8. Photograph of the structure (enclosed) :
Plan form (cc) : $16.5 \times 1.6 = 26.4m^2$
8/8/17


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

104
25

FORMAT FOR VERIFICATION REPORT
(Right hand side/Left hand side)

1. Name of the owner of the structure : M. Nyodee
2. Chainage/Location of the structure : 30800 - 30900
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : 4+2
5. Length of the structure (mtr) : 5.1
- a) Itanagar end (mtr) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2.4
7. Total area of the structure in square metre : 12.24m²
8. Photograph of the structure (enclosed) :



Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



Extra Assistant Commissioner
Itanagar Capit. Complex
Itanagar (A.P)

103 24

FORMAT FOR VERIFICATION REPORT
(Right hand side/Left hand side)

1. Name of the owner of the structure : T. Riba
 2. Chainage/Location of the structure : 30800 - 30900
 3. Type of structure (whether RCC/SPT/MIBT/OBT):
 4. No. of Floors :
 5. Length of the structure (mtr) : 3.8
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
 6. Breadth of the structure (mtr) : 4.8
 7. Total area of the structure in square metre : 27.84m²
 8. Photograph of the structure (enclosed) :
 - : 2.5 x 1.6 = 4m²
 - : 2.6 x 3.1 = 8.06m²
 - : 12.2 x 1.8 = 21.96m²
- SPT Bldg.
Rcc Bldg.
Rcc Bldg.


Executive Engineer
Naharlagon Highway Division
PWD:AP,Nirjuli.



Extra Assistant Commissioner
Itanagar Capit. Complex
Itanagar (A.P)


FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

102 2nd

1. Name of the owner of the structure : Ruben Anspi
2. Chainage/Location of the structure : 20800 - 20900
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : G+1
5. Length of the structure (mtr) : 18
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 1.9
7. Total area of the structure in square metre : 34.2 m²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

28

101

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure : Taje Api
2. Chainage/Location of the structure : 30900 - 31000
3. Type of structure (whether RCC/SPT/MIBT/OBT): Boundary wall
4. No. of Floors :
5. Length of the structure (mtr) : 35.8m
- a) Itanagar end (mtr) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2
7. Total area of the structure in square metre : 71.6m²
8. Photograph of the structure (enclosed) :

c.c. plate form
Septic tank
Rcc wall
MIBT bldg

35.8 x 7.4 = 264.92
4 x 3 = 12m²
6.8 x 2 = 13.6m²
9 x 3 = 27m²

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)


FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

100

29

1. Name of the owner of the structure : (Takkal) Pakhal Koyu
Marde
2. Chainage/Location of the structure : 30900 - 31000
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 11.3
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 4.8
7. Total area of the structure in square metre : 54.26ms²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)


99
30

- 1. Name of the owner of the structure : Mr. Yabe Yosa
- 2. Chainage/Location of the structure : 30,900 - 31000
- 3. Type of structure (whether RCC/SPT/MIBT/OBT):
- 4. No. of Floors : 413
- 5. Length of the structure (mtr) : 6.7
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
- 6. Breadth of the structure (mtr) : $(4.910)/2 = 2.45$
- 7. Total area of the structure in square metre : $16.415 m^2$
- 8. Photograph of the structure (enclosed) :

Steel StairCase
Rec Bldg.
Rec h/tak

3.5 x 1
9.8 x 3.7 (413) = 36.26 m²
2 x 2 = 4 m²
52.675 m²


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

32
95

1. Name of the owner of the structure : Khoda Yari²
2. Chainage/Location of the structure : 31000- 31100
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 16.8
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2.6
7. Total area of the structure in square metre : 43.68m²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.




Extra Assistant Commissioner
Itanagar Capit. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

32

47

1. Name of the owner of the structure : R K M Hospital
2. Chainage/Location of the structure : 31000 - 31400 -
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 7.3
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 1.4
7. Total area of the structure in square metre : 10.22 m²
8. Photograph of the structure (enclosed) :

b/w wall (brick)
MIBT
b/w wall
-do-

: 199m
: 6 x 3.1 = 18.6 m²
: 106m
: 57m

wall = 360m x 2 = 720 m²

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

(Signature)
(Raj An. Sover)


(Signature)
Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

96 33

1. Name of the owner of the structure : NGURANG TAKA
2. Chainage/Location of the structure : 31400 - 31500
3. Type of structure (whether RCC/SPT/MIBT/OBT): slab
4. No. of Floors : 6/3
5. Length of the structure (mtr) : 3.8
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : $(1.4 + 0) / 2 = 0.7$
7. Total area of the structure in square metre : $2.66m^2$
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



08/7/15



Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)

95 35

FORMAT FOR VERIFICATION REPORT
(Right hand side/Left hand side)

1. Name of the owner of the structure : Nyaben Ete
2. Chainage/Location of the structure : 31400 - 31500
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : G+3
5. Length of the structure (mtr) : 10.6
- a) Itanagar end (mtr) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : $(1.4+0)/2 = 0.7$
7. Total area of the structure in square metre : 7.42 m^2
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capit. Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

94 35

1. Name of the owner of the structure : Name Barang
2. Chainage/Location of the structure : 31400 - 31500
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : G+2
5. Length of the structure (mtr) : 14.5
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 1
7. Total area of the structure in square metre : 14.5m²
8. Photograph of the structure (enclosed) :

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

(Sanskir Pkone)

Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

97 36

1. Name of the owner of the structure : Jenko Gadi
2. Chainage/Location of the structure : 31500 - 31600
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 17.7
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2
7. Total area of the structure in square metre : 35.4m²
8. Photograph of the structure (enclosed) :

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.

Executive Engineer
Itanagar Capital Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

92 37

1. Name of the owner of the structure : Takam Paris
2. Chainage/Location of the structure : 31800 - 31900
3. Type of structure (whether RCC/SPT/MIBT/OBT): StairCase Rcc
4. No. of Floors :
5. Length of the structure (mtr) : 10.4
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : $(13.4 + 0) / 2 = 1.5$
7. Total area of the structure in square metre : 6m²
8. Photograph of the structure (enclosed) :

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Executive Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)


FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

90 38

1. Name of the owner of the structure : Bharat Megu
2. Chainage/Location of the structure : 8800-31900
3. Type of structure (whether RCC/SPT/MIBT/OBT): Slab
4. No. of Floors :
5. Length of the structure (mtr) : 3.4
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 0.5
7. Total area of the structure in square metre : 1.7m²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)


90 39

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

1. Name of the owner of the structure : Marked Market
2. Chainage/Location of the structure : 31900 - 32000
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors : .
5. Length of the structure (mtr) : 3
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 1
7. Total area of the structure in square metre : 3m²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagan Highway Division
PVD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

89 40

1. Name of the owner of the structure : Raju Bhawan
2. Chainage/Location of the structure : 31900-32000
3. Type of structure (whether RCC/SPT/MIBT/OBT): Wall with grill
4. No. of Floors :
5. Length of the structure (mtr) : 63
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) :
7. Total area of the structure in square metre : 2
 - Boulder wall : $63m \times 2m = 126m^2$
 - Iron gate : 1 Nos
 - c.c Plate forms : $10 \times 10 = 100m^2$
8. Photograph of the structure (enclosed) :

Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)


FORMAT FOR VERIFICATION REPORT


(Right hand side/Left hand side)

68 W

1. Name of the owner of the structure : Dani Jany Tommy
2. Chainage/Location of the structure : 32200 - 32300
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 13.6
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 3.7
7. Total area of the structure in square metre : 50.32 m²
8. Photograph of the structure (enclosed) :


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



Shyam Chetry



Extra Assistant Commissioner
Itanagar Capir. Complex
Itanagar (A.P)

58 42

FORMAT FOR VERIFICATION REPORT
(Right Hand Side/Left Hand Side)

1. Name of the owner of the structure : ANSU OFFICE
2. Chainage/Location of the structure : 32100- 32200
3. Type of the structure (whether RCC/SPT/MIBT/OBT) : B/wall
4. No. of floors :
5. Length of the structure (Mtr) : 43m
 - (a) Itanagar end (Mtr) :
 - (b) Banderdewa end (Mtr) :
6. Breadth of the structure (Mtr) : 2
7. Total area of the structure in square meters : 86m²
8. Photograph of the structure (enclosed) :


Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)


(Executive Engineer)
Naharlagun Highway Division
PWD, Nirjuli.

FORMAT FOR VERIFICATION REPORT

(Right hand side/Left hand side)

86 43

1. Name of the owner of the structure : Aries Bank Bldg.
2. Chainage/Location of the structure : 32200 - 32300
3. Type of structure (whether RCC/SPT/MIBT/OBT): Stair Case
4. No. of Floors :
5. Length of the structure (mtr) : 6.9
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 12
7. Total area of the structure in square metre : 8.28m²
8. Photograph of the structure (enclosed) :


✓
Executive Engineer
Naharlagun Highway Division
P.W.D:AP,Nirjuli.


✓
Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

85 400

FORMAT FOR VERIFICATION REPORT
(Right hand side/Left hand side)

1. Name of the owner of the structure : R. K. Khrimay
2. Chainage/Location of the structure : 32300, 32400
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 1.2
 - a) Itanagar end (mtr) :
 - b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 2
7. Total area of the structure in square metre : 2.4ms²
8. Photograph of the structure (enclosed) :



Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.



Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)

84 45

FORMAT FOR VERIFICATION REPORT
(Right hand side/Left hand side)

1. Name of the owner of the structure : R.K. Chinnay
2. Chainage/Location of the structure : 32300-32400
3. Type of structure (whether RCC/SPT/MIBT/OBT):
4. No. of Floors :
5. Length of the structure (mtr) : 29
- a) Itanagar end (mtr) :
- b) Banderdewa end (mtr) :
6. Breadth of the structure (mtr) : 5
7. Total area of the structure in square metre : 14.5m²
8. Photograph of the structure (enclosed) :
- Boundary wall : 22m x 2 = 44m²


Executive Engineer
Naharlagun Highway Division
PWD:AP,Nirjuli.


Extra Assistant Commissioner
Itanagar Capital Complex
Itanagar (A.P)